## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Problem Image Mailbox.

EV270265892US Sheet 1/7 Tel: (212)-596-9000



F1G. 1 PRIOR ART








FIG. 2




EV270265892US Sheet 4/7 Tel: (212)-596-9000

6400





Docket No. MIC-42 Not yet assigned Filed Concurrently herewith Sheet GENERATING MULTI-PHASE CLOCK SIGNALS USING HIERARCHICAL DELAYS Peter F. Snell Regn. No. 52,235 Tel: (2

EV270265892US Sheet 5/7 Tel: (212)-596-9000



F16.5





F16.7